



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

January 19, 2007

Supervisor DRZ

Mine Name: Henefer Red Clay
Operator Name: Interpace Industries, Inc.

Permit number: M0430014
Inspection Date: June 14, 2006
Time: 10:00 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection while in the area.

Inspection Summary:

No mining was occurring at the mine site, nor has there been this year as evidenced by the amount of vegetation growing on site. There was a loader at the stockpile area and there has been recent removal of clay from the stockpile. A phone conversation with the operator indicated that they would begin another mining campaign within the next couple days.

Most of the gravels that had been screened at the mine site have been removed. Berms along the edge of the disturbed area have prevented runoff from leaving the site. Disturbed area markers were still in place.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The site is in compliance at this time. Continue to monitor this site when in the area.

Inspector's Signature

Date: January 19, 2007

LK:pb

O:\M043-Summit\M0430014-Heneferredclay\Inspections\Insp-06142006.doc